

## **RF80-K Service Bulletin**

**July 3, 2014**

Applicable to model RF80-K P/N 121630-001 and model RF80-K (CE) P/N121630-006

### **Subject: RF80-K Circuit Board Replacement**

---

The RF80-K contains 3 circuit boards; the control board, driver board and display board. When replaced, all 3 boards must be properly installed and calibrated, with adjustments made to all 3 boards, using specialized test fixtures, equipment and procedures, not available to end users.

As stated in the RF80-K Operator's Manual, if any calibration tolerances are exceeded during the annual calibration verification procedure, the unit should be sent to a Factory Authorized Christie Repair and Calibration Facility. Replacement of circuit boards in the field is not recommended.

Accuracy, reliability, safety and performance may be compromised. If the RF80-K is still under its 3 year warranty, end user replacement of circuit boards will void the factory limited warranty.

Any RF80-K circuit boards purchased from our company for replacement in the RF80-K are not covered by the factory limited warranty and are non-returnable. Technical support is not available for circuit board replacements. If you are purchasing circuit boards, installation is done at your own risk.

If you have an RF80-K which needs repair, a majority of repairs do not require circuit board replacement. We perform repair to the component level which is significantly more economical than complete circuit board replacement.

If you have any additional questions, please contact us.

Marvel Aero International, Inc.  
Christie Distribution & Service Center  
21 Rancho Circle  
Lake Forest, CA 91630 USA  
Tel: +1 949 829 8264 Fax: +1 949 829 8394  
[www.christiecbcs.com](http://www.christiecbcs.com)  
[smarvel@christiecbcs.com](mailto:smarvel@christiecbcs.com)  
[www.marvelaero.com](http://www.marvelaero.com)  
[info@marvelaero.com](mailto:info@marvelaero.com)